



**State of New Jersey**  
DEPARTMENT OF ENVIRONMENTAL PROTECTION

BCAIN - Initial Notice Section  
401 East State Street  
P.O. Box 435  
Trenton, NJ 08625-0435  
Phone #: 609-633-1464  
Fax #: 609-633-1439



JOHN P. JACKSON  
Commissioner

APR - 1 2008

JON S. CORZINE  
Governor

Michael Gibbs, Site Manager  
EFFEM Services  
100 International Dr  
Mount Olive, NJ 07828

**NOTICE OF DEFICIENCY**

Re: Site Investigation Report for:  
100 International Dr, Mount Olive Twp, Morris County  
SRP PI# 298819, Closure #N07-5481  
EA ID #: NOD080001 - 298819

Dear Mr. Gibbs:

The New Jersey Department of Environmental Protection (Department) acknowledges receipt on September 14, 2007 of the Site Investigation Report submitted pursuant to the Underground Storage Tank (UST Rule) regulations at N.J.A.C. 7:14B and the Technical Requirements for Site Remediation at N.J.A.C. 7:26E.

**Deficiencies**

The Department has determined that the Site Investigation Report reflects the following deficiencies:

1. Description of Deficiency: Pursuant to N.J.A.C. 7:26E-3.13(c)3, failure to include a sampling results summary table, including a table in electronic format, that conforms to the requirements of N.J.A.C. 7:26E-3.13(c)3i-v in the Site Investigation Report. Specifically, the electronic data disk failed the Department's EDSA checker.
2. Description of Deficiency: Pursuant to N.J.A.C. 7:26E-3.9(a)5, failure to properly conduct a Site Investigation of all below grade piping. The piping associated with the medium diesel fuel UST was not sampled.

**Corrective Actions**

You must take the following corrective actions:

1. Submit an electronic data disk in the correct format to the Department within 30 days after receipt of this notice in accordance with N.J.A.C. 7:26E-3.13(c)3i-v. If you need assistance, please contact the Department's Electronic Data Helpline at 609-633-1380.

2. Conduct a site investigation within 30 days after receipt of this notice of all below grade piping in accordance with the requirements of N.J.A.C. 7:26E-3.9(a)5 and submit the results in a Site Investigation Report to the Department.

Note that if deficiencies included herein are not addressed to the Department's satisfaction within the specified time period the Department may assess penalties pursuant to N.J.A.C. 7:26C-10. To determine whether the uncorrected deficiencies will be minor with a period of time to correct or non-minor and subject to penalties, refer to the table at N.J.A.C. 7:26C-10.4(c).

If you require copies of Department Guidance Documents or applications, many of these are available on the Internet <http://www.state.nj.us/dep/srp>. If you have any questions regarding this matter contact Muriel Kiernan Case Manager, at (609) 633-3855 prior to the date indicated.

Sincerely,



---

Rafael Rivera, Supervisor  
BCAIN - Initial Notice Section

cc: Muriel Kiernan, Case Manager  
Gregory A. Brown, Eastern Environmental Engineering Services, Inc.  
Clerk, Mount Olive

ersample\_6-5-644

NJDEP HZSAMPLE Error Report

Table:

D:\HZSAMPLE.TXT modified 08/21/2007 09:14:07 size 559 bytes

Project Lead:  
INS

EDSA user:  
mkiernan

NJDEP Folder:  
HZ079978

Case:

DTST.SRPID: N075481

DB \\Dep-01\main\apps\win32\edsa\NJEMScases.mdb Table altCaseId (from NJEMS query)  
lists

SRP pref\_id\_num: 298819

Pgm Interest Name: INFORMATION SERVICES INTERNATIONAL

Pgm Interest Address/ZIP: 100 INTERNATIONAL DR/07828

Master Site Id: 00018570

Site Name: MARS CORP INFO SERVICES GROUP DIV

Site Address/ZIP: 100 INTERNATIONAL DR/07828

Site County, Municipality: 14 Morris, 27 Mount Olive Twp

Name & date of data set

DTST.Directory: QC307858 DTST.SubmitDate: 08/21/2007

DTST.Desc:

Effem Services ISI/Mars Inc

DTST.Consultant:

Eastern Environmental Engineering Svcs

Time checked:

03/27/2008 09:37

Checker ver:

N:\Apps\win32\Edsa\EDSA Ver6-5-644 Modified 01/07/2008 20:52:34 compiled 01/07/2008  
20:52:34

Messages:

(3)

Rec# Description of Problem

- 1 SAMPTYPE= Soil  
ERROR Invalid entry, see SRP-EDI.
- 2 SAMPTYPE= Soil  
ERROR Invalid entry, see SRP-EDI.
- 3 SAMPTYPE= Soil  
ERROR Invalid entry, see SRP-EDI.